

GREEN MOUNTAIN ENGINEERING, INC.

1438 South Brownell Road

P.O. Box 159

Williston, VT 05495

(802) 862-5590

Town of Monkton, VT - VGS Oversight GME Project No. 26-012

Field Report

July 05, 2016

LOCATION(s): Post Road Access; Rotax Road Access; Hollow Road Access; Old Stage Road, Monkton Road

ONSITE:

Old Stage Road:	Hollow Road (just north):
Jamie L. Simpson, GME	Jamie L. Simpson, GME
(1) JAM Crusher w/oper.	(1) Michels R.O.W. Crew
(2) JAM Articulated Dump Trucks w/oper.	(2) Excavators w/oper.
(2) JAM Excavators w/oper.	(1) Bulldozer w/oper.
(1) JAM Bulldozer w/oper.	
(1) JAM Foreman	

WEATHER:

70 °F, Mostly Sunny

GME HOURS ON SITE:

8:00 – 8:45am (Old Stage Rd.); 8:50 – 8:55am (Monkton Rd.);

9:00 - 9:15am (Rotax Rd.); 9:25 – 9:35am (Post Rd.); 9:45 – 10:00 (Hollow Rd.)

WORK OBSERVED:

No activities were observed on-site at the Monkton Road area or the Post Road access.

Old Stage Road:

- Road still closed to thru traffic. JAM crews on-site working to crush larger rock from pipeline route. Crusher on-site working, crushed material being placed back into the excavation along the pipeline route. Road in fair condition, JAM has certainly placed some crushed rock on road and worked it into the road base. Ruts still exist from heavy equipment. JAM expects to be finished at this site by the end of the week.

Hollow Road:

- Michels R.O.W. crew was working along pipeline route (~Sta. 1395+50 - 1397+50) touching up the pipeline route and improving the surface for easier passage of pipeline crew. There is discussion that the Harsh Sunflower site (~Sta. 1382+00 - 1384+75) will likely be getting horizontally drilled instead of open-cut installation. Has not yet been confirmed from Carl Bubolz (Michels).

Rotax Road:

- Access road from Rotax Road has been constructed and flagged by Michels regarding overhead wires and limits of the easement. Some topsoil stockpiling has been completed from approx. Station 1288+00 – 1294+00. There has been discussion that this area may serve as a hydro-pneumatic pressure test location, however there is no evidence of that equipment at this time.

OTHER: No other interactions.

ONSITE OBSERVATION PHOTOS:



Looking north along Old Stage Road from approx. Sta 1564+00.



Looking north along Old Stage Road from Sta. 1552+00.

ONSITE OBSERVATION PHOTOS:



Looking west at the Rotax Road access road, south of McGuiness property.



Looking east at pipeline route, approx. Sta. 1294+50.

ONSITE OBSERVATION PHOTOS:



Looking north from Post Road access road, ~Station 1424+00 – 1417+00.



Looking south from Post Road access road, ~Sta. 1424+00 – 1432+00.